



- [Home](#)
- Repair Parts
- Splicing Procedure
- Feedback
- [Admin](#)


Back to Results Print

## MODULE-INVERTER 110VAC

**Full Repair Kit: 68137873AA**

No terminal repair kits have been identified.


**End View**



4  
8

5

**Isometric View**



### Removal Tools

A specific removal tool has not been identified.

### Pin Information

Cav	Circuit	Gauge	Color	Function
1	P802	1.0	GN	VOLT AC LINE 2
2	N0	0	NA	NO CONNECT
3	N0	0	NA	NO CONNECT
4	A401	2.0	RD	FUSED B(+)
5	P801	1.0	GN	VOLT AC LINE 1
6	P805	0.35	GN	VOLT AC LINE 3
7	N0	0	NA	NO CONNECT
8	Z910	2.0	BK	GROUND

©2023 FCA US LLC. All Rights Reserved.

Chrysler, Dodge, Jeep, Ram, Wagoneer and Mopar are registered trademarks of FCA US LLC.

FIAT is a registered trademark of FCA Group Marketing S.p.A., used under license by FCA US LLC.