



- [Home](#)
- Repair Parts
- Splicing Procedure
- Feedback
- [Admin](#)

Back to Results Print


SENSOR-OXYGEN 1/2

Full Repair Kit: 68500924AA

No terminal repair kits have been identified.


End View

2



5106

Isometric View



Removal Tools

A specific removal tool has not been identified.

Pin Information

Cav	Circuit	Gauge	Color	Function
A1	K734	22	BR/DG	O2 1/2 PUMP CURRENT
A2	K904	20	DB/DG	O2 RETURN (DOWNSTREAM)
A3	K80	22	BR/TN	O2 1/2 HEATER CONTROL RETURN
A4	K299	20	BR/WT	O2 1/2 HEATER CONTROL SUPPLY

Cav	Circuit	Gauge	Color	Function
A5	K733	22	BR	O2 1/2 PUMP CELL CURRENT TRIM
A6	K141	20	DB/YL	O2 1/2 SIGNAL



©2023 FCA US LLC. All Rights Reserved.
Chrysler, Dodge, Jeep, Ram, Wagoneer and Mopar are registered trademarks of FCA US LLC.
FIAT is a registered trademark of FCA Group Marketing S.p.A., used under license by FCA US LLC.