



- [Home](#)
- [Repair Parts](#)
- [Splicing Procedure](#)
- [Feedback](#)
- [Admin](#)


[Back to Results Print](#)

## MODULE-INVERTER 220VAC


Full Repair Kit: 68496346AA

No terminal repair kits have been identified.

End View



Isometric View



---

## Removal Tools

A specific removal tool has not been identified.

## Pin Information

	Cav	Circuit	Gauge	Color	Function
1	P802	1.0	GN	VOLT AC LINE 2	
2	N0	0	NA	NO CONNECT	
3	N0	0	NA	NO CONNECT	
4	A401	2.0	RD	FUSED B(+)	
5	P801	1.0	GN	VOLT AC LINE 1	
6	P805	0.35	GN	VOLT AC LINE 3	
7	N0	0	NA	NO CONNECT	
8	Z910	2.0	BK	GROUND	

©2023 FCA US LLC. All Rights Reserved.

Chrysler, Dodge, Jeep, Ram, Wagoneer and Mopar are registered trademarks of FCA US LLC.

FIAT is a registered trademark of FCA Group Marketing S.p.A., used under license by FCA US LLC.