



LAMP-DRL LEFT

Harness Family: Dash
Color: BLACK
Gender: MALE
Part Number: 34899-6120

Part Description:
Connector No: D2690A
Option: PREMIUM

Repair Kit Part Number:
Cavity Count: 6
Available Views: [Location View](#)

Mating Side:**Isometric View:****Wire Insertion Side:**



NOTE: When connector cavities are identified as "NO CONNECT" in the following table, there may be "Dummy (blunt cut) wires" or Cavities may be "Open", "Plugged, or "Flashed over" depending on vehicle option content.

Pin	Circuit	Wire Color	Gauge/Size	Function	Option
1	L551	BG/BN	0.35	LEFT FRONT LIGHTING FAULT SENSE	PREMIUM
2	L61	WH/GN	0.75	LEFT FRONT TURN LAMP DRIVER	
3	Z905	BK	0.75	GROUND	
4	L77	WH/BN	0.75	LEFT FRONT PARK LAMP DRIVER	
5	L58	WH/YE	0.75	LEFT DRL LAMP DRIVER	
6	Z905	BK	0.75	GROUND	